

Office of the Chief Fire Officer, Bengaluru-East Zone, Karnataka Fire & Emergency Services, No.04, Commissariat Road, Bengaluru-560 025.



No. 102/CFO/Bng-East/FSR/2020

Dated: 10-02-2020.

ANNEXURE – B Group - B Educational Buildings

To,
The Authorized signatory,
M/s. Swamy Vivekananda Educational &
Social Wellfare Trust ®
Sy. No.29/3 & 10/4, Thelagarahalli,
Vanakanahalli Post, Anekal Taluk,
Bangalore-562 106.

Sir,

Sub: Issue of "Fire safety recommendation" to "M/s. Swamy Vivekananda Central School (CBSE), Sy. No.29/3 & 10/4, Thelagarahalli, Vanakanahalli Post, Anekal Taluk, Bangalore-562 106" - reg.

Ref: 1) Your request letter dated: 16-01-2020.

2) Inspection report No.14/DFO/E-city/FSR/2020 Dt: 30/01/2020.

<<<>>>

With reference to the subject above cited, the premises of M/s. Swamy Vivekananda Central School (CBSE), Sy. No.29/3 & 10/4, Thelagarahalli, Vanakanahalli Post, Anekal Taluk, Bangalore-562 106. was inspected by the District Fire Officer, Electronics City Fire Station, Bengaluru on 25-01-2020 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

Part-A. Details of the building / premises :-

01	Name and Address of the Applicant.	:	The Authorized signatory, M/s. Swamy Vivekananda Educational & Social Wellfare Trust ® Sy. No.29/3 & 10/4, Thelagarahalli, Vanakanahalli Post, Anekal Taluk, Bangalore-562 106.
02	Name and Address of the premises.		M/s. Swamy Vivekananda Central School (CBSE), Sy. No.29/3 & 10/4, Thelagarahalli, Vanakanahalli Post, Anekal Taluk, Bangalore-562 106.
03	Name and address of the Building owner		M/s. Swamy Vivekananda Educational & Social Wellfare Trust ® Sy. No.29/3 & 10/4, Thelagarahalli, Vanakanahalli Post, Anekal Taluk, Bangalore-562 106.

East *

Number of floors		Block-1 : Ground & 1 Upper Floor.	
		Block-2 : Ground & 1 Upper Floor.	
		Office Building : Ground floor only.	
Floor-wise details of occupancy:-			
Block-1 Ground floor	:	5 Class rooms & 1 Staff room.	
1 st floor	:	6 Class rooms.	
Block-2	:	6 Class rooms.	
	:	4 Class rooms, 1 Library & 1 lab.	
Ground floor		1 Office room.	
Height of the building Block -1 & 2		07.20Mtrs.	
Office		03.50Mtrs.	
Site area	:	7000.00Sq.Mtrs.	
Built-up area of each floor:-			
Block-1		office with all established the second secon	
Ground floor	:	336.00Sq.Mtrs.	
1 st floor	:	336.00Sq.Mtrs.	
Block-2 Ground floor		383.00Sq.Mtrs.	
1 st floor	:	383.00Sq.Mtrs.	
Office Building		24.00Sq.Mtrs.	
	-		
Total built up area			
West (Front)			
East (Rear)		: 06.00mtrs. Wide Thelagarahalli village road.	
North (Side)		: Vacant land.	
South (Side)		Vacant land.	
	Block-1 Block-2 Ground floor 1st floor Office Building Ground floor Height of the building Block -1 & 2 Office Site area Built-up area of each floor:- Block-1 Ground floor 1st floor Block-2 Ground floor 1st floor Office Building Ground floor 1st floor Office Building Ground floor 1st floor Description of the building Ground floor Surrounding properties:- West (Front) East (Rear) North (Side)	Floor-wise details of occupancy:- Block-1 Ground floor : 1st floor : Office Building Ground floor : Height of the building Block -1 & 2 : Office : Site area Built-up area of each floor:- Block-1 Ground floor : 1st floor : Office : Site area Suift floor : 1st floor : 1st floor : 1st floor : 1st floor : Morth floor : Office Building Ground floor : 1st floor : Description: West (Front) : East (Rear) North (Side) South (Side)	

12.	Set-back area available around the building :-		
	West (Front)	•	02.60Mtrs.
	East (Rear)	:	01.20Mtrs.
	North (Side)		Min 30.00Mtrs.
	South (Side)		05.90Mtrs.

<u>Part-B.</u> On inspection of this School premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view:-

SI. No. (1)	Details (02)		Existing (03)	Recommendations (04)
01.	Accessibility to the premises	18.00mtrs. W located on th	is accessible from ide Thalli Main road ne western side. The ed to carry the weight	Adequate.
02.	No. of entrances	1 Entrance has	been Provided.	Complied.
03.	Width of entry / exit	been provide	Main road located on	Complied.
04.	Diesel generators.	No	t provided.	Not applicable.
05.	No. of staircases available	Nos. of staircases	Block-1:1 No. Block-2:1 No.	Complied.
	where he attribute the same	Width of staircases	Each of 01.60mtrs.	
		Width of treads	Each of 25cms.	
	period in the state of the stat	Height of risers	Each of 15cms.	
	a stated the state of	Nos. of riser per flight	Each 18nos riser per flight.	
	nce Put il Flango Luci - Meriliya 3	Height of handrails	Each 0.90mtrs.	
		Head room	Min. 2.30mtrs.	

East

06.	No. lifts and its capacity.	Not provided.	Not applicable.		
07.	Fire extinguisher	In all 15Nos. ABC type fire extinguishers each of 4kgs. Capacities, 04Nos. ABC type fire extinguishers each of 6kgs capacities & 01No. CO ₂ type fire extinguisher of 4.5kgs capacity has been provided.	Complied.		
08.	Public address system	Not provided.	Public Address System with tw way communication facility shall I provided near each staircas landing of each floor in ea- building and its control panel ground floor of the building shall I provided.		
09.	First aid Hose reel hose.	Not provided.	Hose reel hose of 19mm size and of adequate length to reach the farthest point of the floor near each staircase at each floor of each building shall be provided with shut off branch having a nozzle of 5 mm size. Each hose reel hose system shall be connected to an overhead tank of minimum 10,000 liters capacity with one booster pump capable of delivering 450 liters of water per minute.		
10.	Escape routes	Not marked.	Escape routes shall be marked at each floor of each building to guide the students/staffs in case of any emergency to safer places.		
11.	Fire order	Not displayed.	Notice board indicating with the details of action to be taken by the staff/students in case of an emergency/fire shall be displayed near the staircase landing at each floor of each building with telephone number of Electronic city fire station i.e. 22971576 and 101 of nearby services.		

12.	Fire fighting training	Not trained.	40% of the employees should get trained in fire prevention & Fire Fighting at the R.A Mundkur fire & Emergency Services Academy, B.G
10			Road, Bengaluru.

Under the circumstance stated above, there is No Objection to run education activities in above addressed school building subject to the condition of providing additional fire fighting equipments and fire precautionary measures as shown in column No.4 of Part-B as stipulated in NBC-2016 and then intimate to this office within 90 days positively without fail. "This Fire safety recommendation Certificate is valid Only for One Year from the date of issue and is renewable without fail".

Bengaluru Con East Zone *

Chief Fire Officer
Bengaluru East Zone
Bengaluru

Yours faithfully,

Copy to the District Fire Officer, Electronics city Fire Station, Bengaluru.